


Solder Instruction

- 1. Cable should be prepared for soldering. The cable/wires must be pretinned.
- 2. Insert cable/wire into solder cup.
- 3. Operate the soldering iron at 350 °C, 100 Watt max. and use a pencil tip.
- 4. Apply some solder to the solder tip of the soldering iron.
- 5. Put tip to wire in solder cup.
- 6. After 1 second bring in solder.
- 7. Heat for 5 seconds longer. Do not heat contact more than 6 seconds in total.
- 8. Remove soldering iron.
- 9. Wait until solder gets rigid again.
- 10. Do not solder adjacent contacts consecutively, alternate position within the connector to minimize heat build up.

RECOMMENDED PANEL CUT OUT



г	I	_									1		0.4	
	THIS DRAWING MAY NOT BE COPIED OR REPODUCED IN ANY WAY, AND MAY NOT BE PASSED ON TO A THIRD PARTY WITHOUT WRITTEN PERMISSION. WRATTEN PERMISSION.	DO NOT ALTER CAD DRAWING BY HAND					tolerance			\triangle	scale:		3:1	
										W	material:	SE	E SHEET 1	
									dim. i	n mm				
								date	nam	е	title:			
							drawn	11.06.14	Henne	RECOMMENDED F		PANEL CU	T-OUT	
							appd.	12.06.14	Lehmenl	kühler	D-SUB COMBINATION MALE 2W with threaded insert and hexlocking		ON MALE 2W2	CP
							norm						nd hexlocking s	crew
							d-old				dwg no:			DIN-
							_	45 =		151/11/16	00	A3		
			а	a Original				7 =		15K1A1506		sh:2/2		
			rev.	description	date	name	•				part no:	SEE	SHEET 1	
_		Λ Λ									В			Λ .

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

CONEC:

602W2CPXX61B30X