


Solder Instruction

- 1. Cable should be prepared for soldering. The cable/wires must be pretinned.
- 2. Insert cable/wire into solder cup.
- 3. Operate the soldering iron at 350°C, 50 Watt max. and use a pencil tip.
- 4. Apply some solder to the solder tip of the soldering iron.
- 5. Put tip to wire in solder cup.
- 6. After 1 second bring in solder.
- 7. Heat for 3 seconds longer. Do not heat contact more than 4 seconds in total.
- 8. Remove soldering iron.
- 9. Wait until solder gets rigid again.
- 10. Do not solder adjacent contacts consecutively, alternate position within the connector to minimize heat build up.

RECOMMENDED PANEL CUT-OUT



| | - | GmbH | HAND | | | | | tolerance | | 7 | scale: 4:1 |
|---|------------------------------|----------|---------|----------|-------------|------|------|-----------|------------|-------------------------|-----------------------------------|
| | OR NOT THOU | | | | | | | | | | material: SEE SHEET 1 |
| E COPIED OR | 7 . 🖽 | CONEC | ₽ [| | | | | | | dim. in mm | |
| | | 당 년 | NG. | | | | | | date | name | title: |
| | AND AND PART | 우 | DRAWING | | | | | drawn | 22.09.2015 | Heinrich | RECOMMENDED PANEL CUT-OUT |
| | VOT B WAY, IHIRD | | | | | | | appd. | 23.09.2015 | 2015 Fischer D-SUB FEMA | D-SUB FEMALE HD 44pos. SOLDER CUP |
| | NO TO | <u>6</u> | 8 | | | | | norm | | | with closed 4-40 UNC thread |
| | G M/ IN A OT N MISS | | ¥ | | | | | d-old | | dwg no: | dwg no: DIN- |
| THIS DRAWIN REPRODUCED BE PASSED ON WRITTEN PERI | MIN G D O I | ₫ : | AL | | | | | ĺ | | 15K1A1676 | |
| | ERST | | а | Original | | | CON | | sh: 2 | | |
| | THIS REPR BE PA | | | rev. | description | date | name | 4 | 771 | | part no: SEE SHEET 1 |

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

CONEC: 15-007873