


SYMBOL DEFINITION		MISSING SYMBOLS	
A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL DOES NOT REQUIRE INSPECTION. IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.	TOTAL NO OF INSPECTIONS REQUIRED	NO MISSING SYMBOL NUMBER	
	LAST NO. USED		
	27		
	24		

DATE		REV		W/P		CHG		ZONE		REVISION HISTORY		AUTH		DR		APVD	
02AP02		R		001		-		-		WAS PE097496 AND RELEASED		223146		FRG		FRG	
16AP02		R		001		AA		-		NUT PN WAS 12020097 IN NOTE# 3		223929		RAB		RAB	



Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

[Aptiv:](#)

[15434718](#)